



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



UM-3732-98 1998 Oldsmobile Intrigue

In-depth Vehicle Occupant Report

The University
of Michigan
Transportation
Research Institute

UMINOR



DISCLAIMERS

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points are coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Case Vehicle (A): 1998 Oldsmobile Type: Intrigue, 4-door sedan

Driver: 38-year-old female

CDC: 01-FDEW-2

Situation

(Slide 1) Case vehicle (A) was traveling in the westbound on-ramp preparing to merge into traffic on a four-lane divided highway with a speed limit of 70 mph. (Slides 2, 3) The driver of case vehicle (A) reportedly swerved to the right, while braking to avoid a pedestrian on the on-ramp. Case vehicle (A) entered a counterclockwise yaw, crossed the westbound traffic lanes, and struck a concrete median barrier with its front end. Case vehicle (A) came to rest on the paved shoulder on the south side of the roadway facing west.

Using the SMASH accident-reconstruction program and c-values measured for (slides 4, 5, 6, 7, 8,) case vehicle (A), the following impact severity was calculated:

		Calculated Velocity Change - kph (mp				
Vehicle	Variable	Total	Longitudinal	Latitudinal		
Case Vehicle (A)	EBS	20 (13)	-16 (-10)	-13 (-8)		

Exterior Damage

(Slides 9, 10, 11, 12, 13, 14) Damage to case vehicle (A) was moderate. Direct-damage length was 141 cm and began at the right-front bumper corner. The maximum crush was 29 cm and occurred 25-cm inboard from the right front bumper corner. The front bumper and headlight assemblies were damaged. The hood was crushed and the latch released. The left and right hood hinges were damaged, but did not separate from the hood. The rear edge of the hood was elevated, but did not contact the windshield. The right and left fenders were damaged. There were stress cracks in the lower right corner of the windshield.

Interior Damage

(Slides 15, 16, 17, 18, 19, 20, 21, 22, 23) This vehicle was equipped with steering-wheel and passenger frontal-impact airbags, which deployed during the frontal impact. No damage was noted to the airbag skins or their module doors/flaps. (Slide 24) The steering-wheel rim and spokes were not damaged. No intrusions were noted. (Slides 25, 26, 27, 28, 29) Damage to the interior of the vehicle was limited to that caused by the deploying airbags.

Occupant Injuries and Kinematics

The 38-year-old female driver was reportedly wearing the available 3-point belt. On impact, she moved forward into the belt restraint and the deploying airbag. She sustained a contusion to her left breast from contact by the shoulder belt. She sustained an abrasion to her inner left elbow, probably from contact by the deploying airbag. She sustained a contusion over her abdomen from loading by the lap belt. (Slide 30) She sustained an abrasion and a contusion to her left knee from contact with the underside of the steering column. She sustained a sprained right ankle, probably from contact with the floor pan, and a laceration to her ankle from contact with the bronze hook of her hiking boot.

(Slide 31) The attached table summarizes the injuries sustained by the driver.

Occupant: Driver Restraints: 3-point belt worn; airbag deployed

Age: 38 years Stature: 167 cm (5 ft 6 in)

Sex: Female Mass: 70 kg (155 lb)

	Injury Source				
Injury Description	A.I.S.	Definite	Probable	Possible	
Contusion to left breast	1	Shoulder belt			
Abrasion to inner left elbow	1		Deploying airbag		
Contusion over abdomen	1	Lap belt			
Contusion to left knee	1	Underside of steering column			
Abrasion to left knee	1	Underside of steering column			
Sprained right ankle	1		Floor pan		
1-cm laceration to right ankle	1	Bronze boot hook			
				4	
				·	
Maximum A.I.S. Level	1				
Injury Severity Score	<u>2</u>				

VERSION 05 - 1996	Administrative AD-1
TEAM CODE ACCIDENT ID VEHICLE NUMBER MODULE FORMAT FORM VERSION A D 1 1 1 1 5 1 1 1 1 1 1 1 1	NO. OF CASE VEHICLES IN ACCIDENT NUMBER OF SLIDES TEAM REPORT NUMBER $ \frac{Um-3732-98}{18} $
SPECIAL STUDY (00) None (01) Offset Frontal (98) Not Applicable	36 39
DATE OF FIELD INVESTIGATION: INVESTIGATOR: LOCATION WHERE VEHICLE WAS CIRCLE PHOTO RECOR SLIDES NEGATIVES POLAROIDS REPORT PREPARED BY:	M1


Duplicate columns 1-8 Module G Format C from the previous card. 9 10 1:	1 12	GENERAL INFORMATION	GI-1
TIME DATE OF COLLISION HOUR OF COLLISION (24 HOUR CLOCK) LOCATION STATE: STATE FIPS CODE	· · ·	ENVIRONMENTAL CONDITIONS CONSTRUCTION ZONE (0) NO (1) YES (9) UNKNOWN ROAD ALIGNMENT VERTICAL PLANE (1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN ROAD ALIGNMENT	<u></u>
AREA (1) URBAN (2) RURAL (9) UNKNOWN	23 24	HORIZONTAL PLANE (1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER: (9) UNKNOWN	1 22
ENVIRONMENTAL CONDITIONS LIMITED-ACCESS HIGHWAY (0) NO (1) YES (9) UNKNOWN	26	SURFACE COVERING (10) DRY (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	ĪÕ
ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE) (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN	<u>5</u>	(31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN VISIBILITY LIMITATION (FOR CASE VEHICLE)	
INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR (8) NOT APPLICABLE .	₹	(0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION (5) GLARE	Φ
TYPE OF ROAD SURFACE (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN	29	(6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN VISIBILITY OBSTRUCTION (FOR CASE VEHICLE)	6
ROAD DEFECTS (0) NO (1) YES (9) UNKNOWN	<u>*</u>	(0) NONE (1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE (9) UNKNOWN	<u>v</u>

GENERAL INFORMATION GI-2 ENVIRONMENTAL CONDITIONS MECHANICAL MALFUNCTION SPEED LIMIT WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-6035 (3) 61-70 40 (0) NO (4) 71-79 45 (1) YES (2) YES, DID NOT CONTRIBUTE (5) 80-85 50 TO ACCIDENT (6) 86-90 55 (7) 91-105 60 (9) UNKNOWN (8) OVER 105 65 (9) UNKNOWN **PRECIPITATION** THE FOLLOWING SECTION SHOULD BE FILLED (0) NONE OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED. (1) RAIN (2) SNOW CIRCLE ITEMS INVOLVED. SUPPORT ANY (3) HAIL (4) FREEZING RAIN/SLEET ITEMS CIRCLED WITH COMMENTS. (7) OTHER: (9) UNKNOWN **BRAKE SYSTEM DRIVER CONTROLS** RATE OF PRECIPITATION **EXHAUST SYSTEM POWER TRAIN** (1) LIGHT/MIST **FUEL SYSTEM** STEERING SYSTEM (2) MODERATE (3) HEAVY (8) NOT APPLICABLE SUSPENSION SYSTEM VISIBILITY ITEMS (9) UNKNOWN **ELECTRICAL SYSTEM** TIRES **TEMPERATURE** THROTTLE CONTROLS 9 **UNKNOWN** (0) BELOW -15° C BELOW 5° F OTHER: (1) -15 TO -6 5 TO 22 (2) -5 TO -1 23 TO 31 (3) 0 TO 2 32 TO 36 (4) 3 TO 5 37 TO 41 COMMENTS: (5) 6 TO 15 42 TO 59 (6) 16 TO 25 60 TO 77 (7) 26 TO 35 78 TO 95 (8) OVER 35 OVER 96 (9) UNKNOWN **CROSSWIND** (0) NONE (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN LIGHT CONDITIONS (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN

		GENERAL INFORMATION	GI-3
CRASH DETAILS CASE VEHICLE AND OBJECT (0) NO (1) YES (9) UNKNOWN	45	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY	
CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN	Q	(4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	53
(9) UNKNOWN CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT) (0) NO (1) YES (9) UNKNOWN	<u>a</u>	DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	ā
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO (1) YES (9) UNKNOWN	<u> </u>	DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	. \$ 0
CASE VEHICLE AND CONTACTED STOPPED VEHICLE (0) NO (1) YES (9) UNKNOWN	<u>"</u>	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	Φ
STOPPED CASE VEHICLE AND CONTACTED VEHICLE (0) NO (1) YES (9) UNKNOWN	<u>s</u>	LIST IMPAIRMENTS MENTIO	NED:
TOTAL NUMBER OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH (8) 8 OR MORE (9) UNKNOWN	<u>\$</u>	POST - CRASH DETAIL MANNER CASE VEHICLE LEFT SCENE	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE) (0) NO (1) YES (9) UNKNOWN	<u>z</u>	(1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN	30

ACCIDENT SCHEMATIC

ACCIDENT DESCRIPTION: Cuse vehicle (A) was traveling in the westband on-ramp CASE VEHICLE (A): 1998 Oldsmobile	Intrique G
preparing to merge into traffic on a divided highway. The driver surved right to OTHER VEHICLE (B):	I
avoid a pedestrian on the on-ramp. Case vehicle (A) entered a counter clockwise THIRD VEHICLE (C): N/A	
you, crossed the westbound traffic lanes and struck a concrete barrier with its front end and came to rest	
on the paved shoulder on the south side of the road facing west.	(4)
	NORTH



Duplicate columns 1-8 from the previous card. Module O V Format 0 1 12	OTHER VEHICLE	OV-1
MAKE:	CARGO:	
MODEL:		
VIN		do a carperanega, see soci
MANUFAC/BODY CODE MAKE/MODEL CODE MODEL YEAR 1 9	VEHICLE TYPE PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT	54 55
VEHICLE MASS (kg)	(28) INTERMEDIATE (29) FULL	
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN) 49	MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107°, E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107°, E.G. PANEL TRUCK SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (17) PICKUP CAR WITH CANOPY/SHELL COVER (21) MOTOR HOME (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (23) PICKUP CAR WITH SLIDE-IN CAMPER	
TRAVELING SPEED (km/h) (000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER	
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	(33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S) BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACITY) (44) STREETCAR (ON TRACKS) (68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER) (99) UNKNOWN	-
	WHEELBASE <i>(cm)</i> (999) UNKNOWN	56 57 58

Duplicate columns 1-8 from the previous card. Module O V Format 0 2 11 12		OTHER VEHICLE	OV-2
ORIGINAL SPE	ECIFICATIONS		
Wheelbase cm	Front Overhang	22 - 24	cm
Curb Weight kg	Rear Overhang	25 77	cm
Average Track Width cm	Undeformed End Width	(UEW)	cm .
Overall Length cm	Engine Displacement	31 32	Ĺ
Overall Width (OAW) cm	Engine: # of Cylinders	33 34	•
VEHICLE	DAMAGE		
N/A			
. //-			
•			
FRONTAL CRA	ASH OVERLAP		
Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.	Direct Damage Length (I	ODL)	cm
Front-End Overlap (Percent) = DDL UEW		36 39	%
Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEV OAW	v)		%

Duplicate columns 1-8 from the previous card. Module V D Format 0 1 11 12	VEHICLE DESCRIPTION VD)-1
MAKE: Oldsmobile	CARGO: None per driver	
MODEL: Intrigue	- Stellmann K.	
VIN 13		2
MANUFAC/BODY CODE	STOLEN VEHICLE	
MAKE/MODEL CODE 0629	(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<u>8</u>
MODEL YEAR 1 9 9 8	(c, c.n.a.c.n.	
VEHICLE MASS (kg) $\frac{0}{41}$ 0 1 5 5 4	,BODY STRUCTURE	
ODOMETER (km) 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	(1) BODY & FRAME (2) UNITIZED (3) INTEGRAL-STUB FRAME (4) BODY & PLATFORM FRAME (E.G. VW BUG)	61
(ENTER 9'S IF UNKNOWN) 54	(5) PARTIALLY UNITIZED (7) OTHER: (9) UNKNOWN	
TRAVELING SPEED (km/n) (000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRANSMISSION (0) NONE (1) AUTOMATIC (2) MANUAL (9) UNKNOWN	1 =====================================
VEHICLE TYPE		
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE (ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE	LOCATION OF TRANSMISSION SELECTOR LEVER (1) FLOOR (2) CONSOLE (3) COLUMN (7) OTHER: (9) UNKNOWN	
(18) OTHER PASS. VEH. : (19) PASSENGER VEHICLE, TYPE UNKNOWN	STEEDING	1
MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP. SCOUT. BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINN) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME	STEERING (1) POWER (2) MANUAL (9) UNKNOWN	64
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE	BRAKES (1) POWER (2) MANUAL (9) UNKNOWN	<u>{</u>
(99) UNKNOWN	(3) OldingOlding	

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	3	WHEELBASE (cm) (999) Unknown 74 75
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE	√ ه	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<u>8</u>	
TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN	2 =	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY <u>OUT-</u> LINING NEW PERIMETER OF VEHICLE AND SHADING THE DAMAGED AREAS ON THE LARGE SKETCH ON PAGE VD-3.
DUAL REAR WHEELS (0) NO (1) YES (9) UNKNOWN	$Q_{\overline{n}}$	USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. 2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE.
ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	7,	3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN TYPE OF ROOF	$\frac{0}{n}$	FRONT OR REAR
(0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	73	ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL)

VD-3

Module V D Format 0 2 VEHICLE DESCRIPTION Duplicate columns 1-8 from the previous card. **ORIGINAL SPECIFICATIONS** Wheelbase Front Overhang **Curb Weight** Rear Overhang


Average Track Width **Overall Length**

Overall Width (OAW) 187

Undeformed End Width (UEW)

Engine Displacement Engine: # of Cylinders

VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

Front-End Overlap (Percent) = DDL UEW

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)

Duplicate columns 1-8 from the previous card. Module D 9 1	A Format 0 2	DAMAGE DA-1		
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC		
EVENT NUMBER	1 - 1			
IMPACT SPEED (km/h)	$\frac{9}{14} \frac{9}{15} \frac{9}{16}$	$\frac{998}{35}$		
ESTIMATED BY	17	<u>8</u>		
CRUSH (cm)	$Q_{\frac{1}{n}}$	$\frac{9}{39} \frac{9}{40} \frac{5}{41}$		
CDC #1	QI FDEW 2	<u>98.00000</u>		
CDC #2	<u>9</u> 8.0000.0	$\frac{9}{4} \underline{3} \underline{0} \underline{0} \underline{0} \underline{0} \underline{0}.\underline{0}$		
	A Format 0 3 0 11 12			
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC		
EVENT NUMBER	8 13			
IMPACT SPEED (km/h)	14 15 16	35 36 37		
ESTIMATED BY	17	38 .		
CRUSH (cm)	18 19 20	39 40 41 .		
CDC #1	21	42 - 48		
CDC #2	28 - 34	49 - 55		
Codes				
EVENT NUMBER (8) NOT APPLICABLE	IMPACT SPEED ESTIMATOR LE (1) INVESTIGATOR	CRUSH (998) NOT APPLICABLE		
(9) UNKNOWN IMPACT SPEED	(2) DRIVER (3) POLICE (4) *CRASH* PROGRAM	(NO VEHICLE/DAMAGE) (999) UNKNOWN		
(998) NOT APPLICA	(5) OTHER COMPUTER PROGRAM BLE SPECIFY:	M CDC		
(999) UNKNOWN	(7) OTHER:	(9800000) NOT APPLICABLE (9900000) UNKNOWN		

Module D A Format 0 1 DAMAGE DA-2 Duplicate columns 1-8 from the previous card. 11 12 10 MAXIMUM SHEET METAL CRUSH (cm) (999) UNKNOWN **FRONT** RIGHT SIDE REAR LEFT SIDE **ROOF OTHER** CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER? NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. (1) YES IMPACT CONFIGURATION OBJECT/VEHICLE CONTACTED **EVENT** IMPACT LOCATION NUMBER (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE FOR CODES, SEE TABLE FOR CODES, SEE TABLE ON PAGE DA-3. (3) ON ROADSIDE ON PAGE DA-4. (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN # 1 #2 #3 #4 47 #5

#6

#7

57

62

DAMAGE DA-3

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND <u>UNKNOWN</u> OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND <u>UNKNOWN</u> OTHER VEHICLE CONFIGURATION

RIGHT SIDE OF CASE VEHICLE

- (41) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE T) (42) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

DA-4

DAMAGE

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS

- NO OBJECT
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- OTHER (DESCRIBE)
- UNKNOWN (99)

PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

SIZE

WHEELBASE

SUB-MINI < 2286 mm (< 90°) 2286 - 2412 mm (90° - 94.9°) SUB-COMPACT 2413 - 2539 mm (95" - 99.9") COMPACT 2540 - 2666 mm (100° - 104.9°) INTERMEDIATE 2667 - 2793 mm (105° - 109.9°) FULL 2794 - 2920 mm (110° - 114.9°) 2921 - 3174 mm (115" - 124.9") LARGE LIMOUSINE > 3175 mm (> 125°)

MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
 - (12) PICKUP
 - (14) SMALL UTILITY (WHEELBASE LESS THAN 107", E.G. JEEP, BRONCO)
 - (15) LARGE UTILITY (WHEELBASE MORE THAN 107". E.G. PANEL TRUCK, SUBURBAN)
 - (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
 - (17) PICKUP CAR WITH CANOPY/SHELL COVER
 - (21) MOTOR HOME
 - (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
 - (23) PICKUP CAR WITH SUDE-IN CAMPER
 - (31) CHASSIS-MOUNTED CAMPER

TRUCK

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SUDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER
- (33) DELIVERY VAN (WALK-IN)
- (34) STRAIGHT TRUCK
- (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

Bus

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 cc (52) 76 125 cc
- (53) 126 250 œ
- (54) 251 500 cc (55) 501 - 750 œ
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE)
- (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER)
- (67) TRAILER, COMMERCIAL (CARGO)
- (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

OBJECT

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE ...
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION (91) GUARD RAIL, MIDDLE OR UNKNOWN
- (92) GUARD RAIL, TRAILING SECTION
- (93) GUARD POST (TIMBER, METAL, CONCRETE) (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

Duplicate columns 1-8 Module C F from the previous card. 9 10	Format 0 1 12		H RECONSTRUCT r ΔV	TION CR-
	CASE VEHICLE P	RIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		47	
ΔV (km/h) TOTAL	$ \underline{0}_{14} \underline{1}_{15} \underline{0}_{16} $	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	48 49 50	66 67 68
LONGITUDINAL*	$\frac{-}{17}$ \bigcirc $\boxed{1}$ $\boxed{6}$	$\frac{\mathcal{G}}{35} \frac{\mathcal{G}}{3} \frac{\mathcal{G}}{35} \frac{\mathcal{G}}{35}$	51 54	69
LATERAL*	<u>-013</u>	<u> 3888</u>		
*NOTE: THESE AV COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>: 0 0 7</u>				
ENERGY DISSIPATED BY CRUSH (ki)	<u>\$\delta\$ \delta\$ 4 \delta\$</u>	<u>8888</u>	59 62	$\frac{\pi}{\pi}$
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	<u>22</u>			
(21) RECONSTRUCTED, LOW	29 30		63 64	
CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE				
CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL				
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE				
(04) ROLLOVER (05) VAULTING				
(06) OTHER TRAVEL IN MORE				
THAN ONE PLANE (07) NON-HORIZONTAL FORCE				
(08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT				
(10) OTHER:				
BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE				
(1) CDC ONLY	5			
(2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC	31		65	
(4) TRAJECTORY & CDC & DETAILED DAMAGE				
(5) NOT RECONSTRUCTED				
COMPUTER_PROGRAM				

Duplicate columns 1-8 from the previous card. Module C R 9 10	Format 0 2		H RECONSTRUC r EBS	TION CR-2
	CASE VEHICLE P	RIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		47	
EBS (km/h) TOTAL	$ Q_{14} \underset{15}{\cancel{2}} \underline{\mathcal{Q}} $	<u>888</u>	48 49 50	66 67 68
LONGITUDINAL*	<u>-016</u>	8888	51 54	69
LATERAL* *NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.	$\frac{1}{2}$	8888	55 58	73 — —
EXAMPLES: 10 km/h = ± 0 1 0 -7 km/h = ± 0 0 Z				
ENERGY DISSIPATED BY CRUSH (4)	<u>@</u> <u>@</u> <u>4</u> <u>8</u> 48,333	888	59 62	
RECONSTRUCTION	48,553			
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	<u>2</u> 2		63 64	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL				
NOT RECONSTRUCTED BECAUSE				_
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE .				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<u>3</u> 1			
COMPUTER PROGRAM SPECIFY: SIM HA A			•	

CRASH RECONSTRUCTION Duplicate columns 1-8 Module C R Format 0 3 CR-3 from the previous card. 10 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS. NOTES: CASE VEHICLE 2. MEASURE C_1 TO C_6 FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS. LOCATOR 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG. 4. USE THE CENTER OF THE WHEELBASE AS THE CG. Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts. Specific Impact No. Location of Direct Damage Location of Field L 13.C. bumber Gyner **C6** C5 **C4** PLANE: C2 (1) Bumper (2) Above Bumper (3) Sill (4) Above Sill (5) Other (9) Unknown **CRUSH PROFILE IN CENTIMETERS** NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line. Direct Damage Specific Plane of Impact C₁ C_2 impact C_3 Length Max Field C₄ ±D C_5 C_6 Number C-Measur. (DDL) Crush + 14 -Freespace 90 - 6 20 G 128 006 018 025 028 029 13 15 16 17 18 19 20 2

	e columns 1-8 previous card.	Module C	R Forma	t <u>0 4</u>	<u> </u>	С	RASH F	RECONS	STRUCT	TION	CR-4
NOTES	2. MEASL IMPACT 3. D IS PC	I CRASH RECO IRE C ₁ TO C ₆ F IS, REAR TO FI DSITIVE IF MEA HE CENTER OF BITTAGE WITH TE	ROM DRIVER RONT IN SIDE II SURED TO A P THE WHEELBA	TO PASSENG MPACTS. OINT FORWA ASE AS THE C	ER SIDE IN RD OF OR '	FRONT OF	R REAR		L	ER VEHOCATOR	
Specific	Impact No.		ocation of	Direct Dar	nage		· · · · · · · · · · · · · · · · · · ·	Locat	ion of Fi	eid L	
PLA	NE: (1) Bumper (2) Above Burr (3) Sill (4) Above Sill (5) Other (9) Unknown	nper		6 5 3 8 8 C	07 12 1			DL UDL			
	NOTE: Each	line in the tab	le below is a	I PROFILE separate rec			ERS plicate col	umns 1 - 1	2 for each	complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Length (DDL)	Damage Max Crush	Field L	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
					<u> </u>						
1											
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
2											

Duplicate columns 1-8 Module W T Form from the previous card.	nat <u>0</u> <u>1</u>	WHEELS AND TIRES WT-1
(0) NO (1) YES (9) UNKNOWN	LF $\frac{\mathcal{O}}{Q}$ RF Q LR Q_{16}	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF P22560R16 RF P23560R16 LB P23560R16
(1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF 4 4 4 4 LR LR	LR F & S D W N I W
(1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER:	FF RR LR	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:		

Duplicate columns 1-8 Module F T Format from the previous card. 9 10 1	0 1	FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	<u> </u>
MAIN TANK LOCATION	322	AUXILIARY TANK LOCATION	88
MAIN FILLER CAP LOCATION	113	AUXILIARY FILLER CAP LOCATION	38
MAIN TANK MATERIAL	1 20	AUXILIARY TANK MATERIAL	$\frac{3}{25}$
(1) LEI (2) WI (3) RIG (4) DU (8) NO (9) UN	BHT OF FRAI AL, RIGHT & IT APPLICAB KNOWN BIT (VERTICA	E OR CENTERED ME LEFT TANKS LE (NOT EQUIPPED) LL)	
(2) WI (3) AB((8) NO	OVE FRAME	OR CENTERED	
(3) PL/ (7) OTI (8) NO	EEL JMINUM ASTIC HER	DES	

Duplicate columns 1-8 from the previous card. Module F _ Format 0 _ 1 10

FUEL LEAKAGE

FL-1

DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

(1) YES COMPLETE PAGE.



	1	11	111	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15			_		21
#2	2 23	_				29 -
#3	30 31	_		_		37
#4	38 39		_			45
#5	46 47			_	——	53

LEAKING COMPONENT

TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

DELIVERY SYSTEM

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO **CARBURETOR OR INJECTOR PUMP)**
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

II COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & **REAR BULKHEAD**
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z.P.&B
- (6) D. DISTRIBUTED (F, P & B)
- (9) UNKNOWN

SECOND DIGIT (LATERAL LOCATION)

- (1) L. LEFT
- (2) C. CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z. RIGHT CENTER (R&C)
- (6) D. DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 10 11	1 12	FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAC (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

Duplicate columns 1-8 Module <u>E</u> <u>D</u> Format <u>(</u> from the previous card. 9 10 11	© 1 EXTERIOR DAMAGE	ED-1
HOOD PERFORMANCE	STEERING COL FLEXIBLE COUPLING	
FOR THE FOLLOWING, USE CODES:	FLEXIBLE COUPLING TYPE	
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	(0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE	9 26
HOOD LATCH <i>(ES)-</i> -RELEASED	(CIRCLE EACH) (7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED	
-DAMAGED	14 COUPLINGDAMAGED	9
JAMMED	COUPLINGDAMAGED (USE CODES FROM HOOD PERFORMANCE) -SEPARATED (COMPLETE)	9
HOOD HINGESLEFT, DAMAGED	16	
-LEFT, SEPARATED (COMPLETE)	• • • • • • • • • • • • • • • • • • • •	
-RIGHT, DAMAGED	ENG COMPART TELESCOPING UNIT	
-RIGHT, SEPARATED (COMPLETE) HOOD REMAINED ON VEHICLE	TYPE OF UNIT (00) NONE INSTALLED (01) - (07) SEE UNITS ON PAGE ED-2 (88) NOT COLLECTED (97) OTHER: (98) EQUIPPED, TYPE UNKNOWN	8 8 20 30
REAR EDGE OF HOODELEVATED	20 (99) UNKNOWN IF EQUIPPED 1 ORIGINAL LENGTH (mm)	
-CONTACTED WINDSHIELD	F (OR H):	
-PENETRATED WINDSHIELD	TELESCOPED LENGTH (mm) G:	
HOOD LATCH LOCATION		
 (1) FRONT OF VEHICLE (2) COWL AREA (3) SIDE (8) NOT APPLICABLE (9) UNKNOWN 	DIFFERENCE (mm) F (OR H) - G (IF LESS THAN 15mm, ENTER *000*.) (888) NOT COLLECTED	
ENGINE OR TRANSMISSION MOUNT SEPARATION (COMPLETE) (0) NO (1) YES (9) UNKNOWN	(991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8

		EXTERIOR DAMAGE	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN LEFT PILLARS	K 8	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES: (0) DOOR DID NOT OPEN	
PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN	
-A-PILLAR, UPPER LOWER		(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRO	
-B-PILLAR, UPPER LOWER		DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR)	
-C-PILLAR, UPPER) = 9	(9) UNKNOWN -FRO	45
-D-PILLAR, UPPER . LOWER	8 = 3 = 3	·	

		EXTERIOR DAMAGE	ED-3
		OTHER REAR DAMAGE	
REAR DOOR REAR DOOR TYPE (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE	<u>Q</u>	WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u>
(4) CLAMSHELL/DISAPPEARING TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN		SPARE TIRE (0) NO SPARE TIRE	<u>8</u>
Hatchback One-way		 (1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (6) NOT COLLECTED (9) UNKNOWN 	51
Two-way or Clamshell Single door		TRAILER HITCH TYPE (0) NO HITCH BALL-AND-SOCKET TYPES (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK)	€
HOW DID DOOR OPEN DURING COLLISION?	Q	(3) BUMPÉR-AND-FRAME (BUT NON-EQUALIZING) (4) LOAD EQUALIZING OTHER TYPES (5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. P/U) (7) OTHER (E.G. CLEVIS-AND-PIN)	
(0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION	8 =	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER	0
 (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN 		(1) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	23
DOOR JAMMED CLOSED (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	4	,,	

		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	g.	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	0	(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM) (98) NOT APPLICABLE (NO DOOR)	
-A-PILLAR, UPPER LOWER -B-PILLAR, UPPER	55 Ø 56 Ø 57	(99) UNKNOWN -FRONT -REAR	
LOWER -C-PILLAR, UPPER		DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	
LOWER	59 Ø 60 Q	-FRONT	Ø = 50 = 50 = 50 = 50 = 50 = 50 = 50 = 5
-D-PILLAR, UPPER LOWER	0 61 A	VAN REAR DOOR TYPE (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT & LEFT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	<u>\$</u>

		EXTERIOR DAMAGE	ED-5
WINDSHIELD DAMAGE		WINDSHIELD MARK ON CASE VEHICLE	
WINDSHIELD CRACKED (0) NO (1) YES (8) NOT APPLICABLE	70	SHADED SOLAR RAY	- -
(9) UNKNOWN WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN) (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	71	SAFTY PAG FLO	-LITE NATED
CRACKED OR BROKEN BY OCCUPANT CONTACT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN EXTENT OF BOND SEPARATION		WINDSHIELD CODE (97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) (99) UNKNOWN	92
(0) NONE (1) 1 - 20% (2) 21 - 40 (3) 41 - 60 (4) 61 - 80 (5) 81 - 99 (6) TOTAL (7) SEPARATED, AMOUNT UNKNOWN (8) NOT APPLICABLE (9) UNKNOWN	Q	ROOF DID T-ROOF/SUN ROOF OPEN DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN	\$
LOCATE AREA OF WINDSHIELD IN & HORIZONTAL) ON THIS DIAGRA	TEREST OF	R DAMAGE WITH DIMENSIONS (VERTICAL WINDSHIELD AS VIEWED FROM INSIDE.	
<u>7</u> 2	8: \frac{8:}{\varphi}	2	7 <u>2</u> R

Duplicate columns 1-8 from the previous card. Module S C Format 9 10	0 1	STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL	-	STEERING WHEEL POSITION AT TIME OF COLLISION	
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	<u></u> 13	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1, 2. O'CLOCK = 0, 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	4 4	(NORMAL STRAIGHT O'CLOCK - P)	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70 - 74 CHALLENGER, 70 - 74 CAPRI, 71 - 77	
STEERING COLUMN OPTIONS		(2) EXAMPLES: CMM, 79 - HORIZON, 79 -	
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	2 16	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED ORIGINAL DIMENSION (mm.)	8 19
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	P	A: DAMAGE DIMENSION (mm) B: DIFFERENCE (mm)	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>Ø</u> 18	A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN ENERGY ABSORBING DEVICE		STEERING WHEEL (CONTINUED)	:
TYPE OF DEVICE * (IF 27 OR 28)		STEERING WHEEL HUB DAMAGE	
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8 23 24	(0) NONE (1) OCCUPANT CONTACT (2) AIRBAG (3) OTHER	Q
ORIGINAL LENGTH (mm) C:		(9) UNKNOWN	
COMPRESSED LENGTH (mm)			
D:			
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE) OR			·
COMPRESSION (OR EXTRUSION) (mm) C - D (OR E) (TOLERANCE: ±10)			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN * (ADD A & B FOR TOTAL COMPRESSION) SHEAR CAPSULE SEPARATION (mm) S (USE AVG. OF LEFT & RIGHT CAPSULES.) LT:	8 8 8 27		
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION (0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	Ø		
COLUMN LATERAL ROTATION (0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	$\frac{\pi}{Q}$		

									INTRUS	SION	IT-1
Location Intrusion	of n	Intruded	Component	Compari Value		asurements Ard Intruded Value		·	rusion	ł	ominant Crush Direction
							=				
						_	=				
			NONE	X			=				
			0010	ier,			=				
			APP			_	=				
							=				
						_	=				
<u></u>							=				
						_	=				
						_	=				
						_	=				
						_	=				
							=				
						_	=				
							=				
						- .	=				
			0	CCUPANT C	ONTA	CT WORKS	HEET				
Contact	Co	Interior omponent ontacted	Occupant No. if Known	Body Region if Known		Supportin					Confidence Level of Contact Point
Α	Col	umn	1	Knee	Cr	acked é	Scut	fed	cover		
В		ee bolster	. 1	Knee	S	acked ¿ Cuffed					
С											
D											
E								•			
F											
G											
Н											
1											
J											

INTRUSION IT-2 VEHICLE OCCUPANT CONTACT DIAGRAM Cracked Escuffed

INTRUSION IT-3

CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.


(1)	LEFT	(3)	RIGHT			INDIVIDU	JAL SEAT
(1)	LEFT	(2)	CENTER	(3)	RIGHT	BENCH:	FULL WIDTH 3 PASSENGER
(1)	LEFT	(2)	LEFT CENTER		RIGHT (3) RIGHT	BENCH:	FULL WIDTH 4 PASSENGER
(1)	LEFT	(2)	CENTER	(5)	RIGHT &	BENCH:	PARTIAL WIDTH, LEFT
	LEFT & SPACE	(2)	CENTER		RIGHT &SPACE	BENCH:	PARTIAL WIDTH, CENTERED
(4)	ENTIRE V	/EH	ICLE WIDTH			CARGO	AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

PASSENGER CAR 5 PASSENGERS

VAN 12 PASSENGER CAPACITY



CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT	INJURY	
NUMBER	NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
· (99)	(00) OR (99)	UNKNOWN IF CONTACT

INTRUSION **IT-4**

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: <u>DO NOT</u> CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

INTERNAL

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS
- (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/
- SEAT-BACK BACK SURFACE (18) SECOND SEAT-BACK SURFACE **SEAT-BACK BACK SURFACE**
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE **SEAT-BACK BACK SURFACE**
- (21) FIFTH SEAT-BACK SURFACE **SEAT-BACK BACK SURFACE**
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

EXTERNAL

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE (46) OTHER (E.G. SPARE TIRE,
- JACK. DESCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

USE ONLY IF ALL THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

(50)WINDSHIELD HEADER

A-PILLAR

ROOF SIDE RAIL

(51)INSTRUMENT PANEL A-PILLAR

DOOR PANEL

(52) INSTRUMENT PANEL

A-PILLAR WINDSHIELD HEADER

(53) DOOR PANEL

B-PILLAR ROOF RAIL

(54)DOOR PANEL

A-PILLAR **ROOF RAIL**

(55) INSTRUMENT PANEL

FLOOR PAN A-PILLAR DOOR FRAME

(56) ROOF RAIL

A-PILLAR

B-PILLAR

WINDOW FRAME

(57) ROOF RAIL

A-PILLAR **B-PILLAR**

C-PILLAR

DOOR PANEL

(58)ROOF

ROOF RAIL WINDOW FRAME

DOOR PANEL

(59)BACKLIGHT HEADER

ROOF

C-PILLAR

THIRD SEAT-BACK

(60)ROOF **ROOF RAIL** A-PILLAR **B-PILLAR** C-PILLAR WINDOW FRAME DOOR PANEL FLOOR PAN

(61)INSTRUMENT PANEL

TOE PAN

WINDSHIELD HEADER

A-PILLAR **ROOF RAIL**

WINDOW FRAME

DOOR PANEL

ROOF

(62)ROOF **ROOF RAIL** C-PILLAR

WINDOW FRAME

FLOOR PAN SECOND SEAT

DOOR PANEL

(63)ROOF RAIL

ROOF

B-PILLAR WINDOW FRAME

FLOOR PAN

DOOR PANEL

SECOND SEAT

FRONT SEAT

(64) ROOF RAIL

ROOF OR CONVERTIBLE TOP A-PILLAR

B-PILLAR

WINDOW FRAME

WINDOW HEADER

(65)WINDSHIELD WINDSHIELD HEADER **ROOF SIDE RAIL**

(66)WINDSHIELD

WINDSHIELD HEADER

A-PILLAR

(98) NOT APPLICABLE

(99) UNKNOWN

	T Format 0 1	-		Intrus	SION IT-5			
WAS THERE OCCUPANT COMP (0) NO <u>DO NOT</u> ANSWER NEXT (1) YES <u>ANSWER</u> NEXT QUESTIC (9) UNKNOWN <u>SKIP PAGE</u> .	OUESTION. <u>SKIP PAGE</u> .	<u>D</u> w	(0) NO <u>COM</u> (1) YES <u>SKI</u> E	PLETE PAGE.	DPHIC?			
	T Format 0 2 11 12 a separate record (card). Du	plicate columns	1 - 12 for each co	mpleted line.				
CODES FO	INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES. CODES FOR B, F, G, H, I, J ON PAGE IT-3 CODES FOR C ON PAGE IT-4 OCCUPANT CONTACT AND INJURY							
A B C INTRUDING A INTRUSION OCC. COMPONENT E NUMBER SPACE NO. OR OBJECT		1			J K CCUPANT INJURY NUMBER NUMBER			
13-14 15-16 17-18	19 20-21 22-23	24-25	26-27	28-29	30-31 32-33			
01								
02								
03								
04								
0 5				·				
06								
0 7	n 7 INTRUSIONS.							
Duplicate columns 1-8 Module 1 from the previous card.	T Format 0 3							
NOTE: IF NO SIDE DOOR INTRUSION, SKIP REMAINDER OF PAGE. SIDE DOOR INTRUSION RESULTED FROM	IF DAMAGE TO DOOR INTRUS INTRUSION NUMBER C	D DOOR CO SION, CODE DAMAGED OMPONENT 1	MPONENT RE COMPONENT DAMAGEI COMPONEN	Γ Π 2	CODES			
INTRUSION NUMBER CAUSE CODES	A	. <u> </u>	<u> </u>	(0)	NONE			
13 15 (1) DIRECT IMPACT	22 23 B 26 27	_	25	(2) I (3) ((4) I (5) I	A-PILLAR B-PILLAR C-PILLAR LATCH/STRIKER HITMESS			
16 18 (2) INDUCED DAMAGE 19 21 (9) UNKNOWN	D	_	33	(8)	OTHER: NOT APPLICABLE UNKNOWN			

Duplicate columns 1-8 from the previous card.

Module 1 T Format 0 2 9 10 11 12

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

- ADDITIONAL PAGE -

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

A INTRUSION NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT			F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8										
09										
10			_							
11			_							
12.			_							
13										
14			_							
15										
1 6										
17										
18			-							
19										
20										
21										
22										
23			_							
24			_							
25										

Duplicate columns 1-8 from the previous card.	Modu	le <u> </u> D	Format 0 1 12		TERIOR DAMAGE	ID-1
со	(1) NO) YES) NO, and		(4) YES, and C (8) NOT APPL (9) UNKNOWN		
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE		YES, and PR		(8) NOT APPL	ICABLE	
T-ROOF/SUN ROOF	0°00°1	Page Page Bur			REAR WINDOW HEADER	<u>Ø</u>
			·		CONSOLES VERTICAL ROOF	Z 7

^{*} MORE THAN ONE ITEM MAY BE NOTED.


Duplicate columns 1-8 from the previous card. Module S T 9 10		2 12	SEATS		ST-1
FRONT SEAT TYPE OF FRONT SEAT (00) NO SEAT (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE	DRIVER 0 5 13	PASSENTR 0 5 15 16	FRONT SEAT-BACK SEAT-BACK TYPE (1) FORWARD FOLDING	DRIVER	PASSENT
(04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE (09) INDIV. BENCH, PASS. WIDE (97) OTHER:			(2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN SEAT-BACK LOCK TYPE	3 30	31
(99) UNKNOWN TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	17	18	(0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN ORIGINAL EQUIPMENT SEATS	19		LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	1 24	35
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN CONTACT OF SEAT BY REAR OCCUPANT	<u>21</u>	\(\frac{1}{2} \)	RECLINER MECHANISM HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	=	37
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN FRONT SEAT DAMAGE (0) NONE			HEAD RESTRAINT HEAD RESTRAINT TYPE		-
(1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	25	26	(0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	38	39
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	$\frac{Q}{z_7}$		REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		<u>Q</u>
FRONT SEAT ROTATION (0) NONE APPARENT	<u>Ø</u>	\$\overline{Q}	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN	2 2	43
(1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	29	HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	<u> </u>	<u></u>

			S	EATS	ST-2
FRONT SEAT ADJUSTMENT	DRIVER	PASSENT	SECOND SEAT (CONT.)	•	
SEAT ADJUSTMENT TYPE (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN ADJUSTMENT PROVIDED (1) 2-WAY	<u>3</u>	47	(0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED		
(2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	48	49	SECOND SEAT-BACK LOCKS	LEFT	Rigi
SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	∑i s	<u> </u>	(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	0	(A)
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN			LEFT OR CENTER, EQUIPPED LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED) i a O i s	8 Q
PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	<u>z</u>	55	RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	\$	\$ 55
SECOND SEAT	LEFT	RIGHT	EQUIPPED	Ø	0
TYPE OF SECOND SEAT (0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT	56	<u> </u>	BACKREST DAMAGED CUSHION DAMAGED	SISO F DE	
(5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	Q se	<u>Ø</u> s9	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position	7	5


Duplicate columns 1-8 Module A B Format 0 11		AIRBAG	AB-
DRIVER SIDE LOCATION OF AIRBAG STEERING WHEEL EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	13	PASSENGER SIDE LOCATION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	1
CONDITION OF AIRBAG STEERING WHEEL (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE POT EQUIPPED OR CONDITION	<u></u>	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED) OR CONDITION	4
DRIVER SIDE AIRBAG STEERING WHEEL TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	19 <u>19</u>	PASSENGER SIDE AIRBAG INSTRUMENT PANEL (GLOVE BOX) TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>Q</u>

AIRBAG AB-2

AIRBAG NUMBER ON DRIVER SIDE:



AIRBAG NUMBER ON PASSENGER SIDE:



NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,

OCCUPANT INFORMATION AND INJURY CLASSIFICATION,

ARE TO BE FILLED IN

FOR EACH CASE VEHICLE OCCUPANT,

WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 from the previous card. Module O C Format 0 11		- OCCUPANT INFORMATION	OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	$ \begin{array}{c c} $	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	38/21
OCCUPANT POSITION		MASS (kg) · (999) UNKNOWN	<u>0</u> 70
ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	HEIGHT (cm) (999) UNKNOWN SEX (1) MALE (2) FEMALE (9) UNKNOWN	27 28 20 20 30
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	17	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA	<u>Ø</u> <u>2</u>
POSTURE (10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT	18 19	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN	<u>Ø</u> 33 34
(50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN		NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH) (9) UNKNOWN	35


		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	36	CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	88
ACTIVE RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED	3 37 3 1 39 2 40	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	98 4
(4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN		HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	1

		OCCUPANT INFORMATION	OC-3
OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	2,	SOURCE OF INFORMATION (0) INTERVIEW (1) HOSPITA (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN	7-

OCCUPANT INFORMATION OC-4

INDICATE LOCATION OF INJURIES.





Duplicate columns 1-8 from the previous card.

Module | C Format 0 1 12

INJURY CLASSIFICATION IC-1

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.


OCCUPANT INJUR	Y CLASSIFICATION
----------------	------------------

						PRIMARY OIC ASSOCI			ASSOCIATED OIC				COMMENTS		
OCCUPANT NUMBER	INJURY NUMBER	PROBAE START V IN 1ST C	BILITY (HOR WITH MOST CONTACT A	IN ORDER OF . IZONTALLY) . PROBABLE REA COLUMN. BLE CONTACT	BODY REGION 1	ASPECT N	LESION 9	SYSTEMORGAN 4	SEVERITY 10	BODY REGION	ASPECT N	LESION つ	SYSTEMORGAN 4	SEVERITY LO	
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
<u>oi</u>	QL	34			C	L	C	Ī	1	_	_	_	_		
1	<u>02</u>	87			Ē	L	Ā	I	1	_		_	_	_	
	03	34			M	M	ر	エ	1						
	04	66			K	L	C	Ī	1						
	05	4.0			Q	R	<u>S</u>	7	1			_	_		
	06	38		Bronze hook on		R	エ	_	1	_	_		_	-	
				buot		_	_	_	± 1		_	_	_		
	Q 7	<u>66</u>				<u>_</u>	4	1	T	_	_	_	_	-	
흳					_	_	_	_	_	_	_	_	_	-	
r each li					_	_	_	_	_	_	_	_	_	-	
e "Occupant Number" for each line					-	_	_			_	_	_	_	-	. .
ipant Nu					_	_	_	_	_		_		_	_	
					_	_	_			_	_	_	_	_	
Duplica					_	_	_		_	_		_	_	_	
					_		_		_	_	_		_		
				•				_							
					_			_	_	_		_	_		
					_		_	_	-	_	_	_	_		
					_	_	_	_	-	_	_	_	-		
					—			_	-	_	_	_		-	

INJURY CLASSIFICATION IC-2

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

FRONT	OF PASSENGER COMPARTMENT	SIDES	
(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
(12)	WINDSHIELD	(19)	
		(13)	
(05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)	(24)	
(54)	UPPER INSTRUMENT PANEL (X)	ν,	
(55)	MIDDLE INSTRUMENT PANEL (Y)	(22)	WINDOW GLASS (SIDE)
(56)	LOWER INSTRUMENT PANEL (Z)	(21)	· · · · · · · · · · · · · · · · · · ·
(81)	ASH TRAY (INSTRUMENT PANEL)	(,	
(02)	GLOVE COMPARTMENT AREA	(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	• • • •	A-PILLAR
• •		, ,	B-PILLAR
(57)	BENEATH INSTRUMENT PANEL	17	C-PILLAR
(53)	PARCEL TRAY	· -,	D-PILLAR
(48)	KNEE RESTRAINT	(17)	DTILLAN
(86)	VERTICAL CONSOLE	FLOOR	
(50)	VERTICAL CONSCIE		T 000
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)		FLOOR
(20)	FOOT CONTROLS (INCL PARKING BRAKE PEDAL)		CONSOLE ON FLOOR OR BETWEEN SEATS
(00)	CTTTDING ACCTION V (COTCOTO ADDA A MAGNAM	• •	TRANSMISSION LEVER ON FLOOR OR CONSOLE
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)	(85)	
(65)	STEERING WHEEL		FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
(66)	STEERING WHEEL COLUMN	(91)	KICKPANEL
(59)	TRANSMISSION LEVER ON COLUMN	_	
		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)	(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	
(84)	PARKING BRAKE HANDLE IN FRONT	• • • • •	COAT HOOK
(67)	IGNITION KEY	, ,	DOME LIGHT
(06)	MIRROR		BACKLIGHT HEADER
(04)	HEATER OR AIR CONDITIONING DUCTS	(68)	
(01)	AIR CONDITIONING OR VENTILATION OUTLET/S)	\ -	ROLL BAR
(08)	RADIO (BUILT IN)	(09)	NOCE BAN
(58)	ADD-ON TAPE DECK, RADIO, A/C	Evenic	OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES		
(00)	HOOF MOONTED CONTROLS CONSOLES	(37)	OUTSIDE SURFACE OF CASE VEHICLE
REAR		40.00	(SPECIFIC AREA UNKNOWN)
	CHOCAGE OF READ INTERNOR	(35)	HOOD OF CASE VEHICLE
,	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
	REAR WINDOW		OUTSIDE MIRRORS, ANTENNA, TRIM)
,,	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
		(64)	TIRES OF CASE VEHICLE
_	R-GENERAL	_	
	TRANSMISSION SELECTION LEVER (LOCATION UNIC.)	BEYOND	CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN	(36)	AREA EXTERIOR TO CAR (SPECIFIC AREA UNIC)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
(07)	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84)	PARKING BRAKE HANDLE IN FRONT		OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
•	·	(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
(50)	REAR SEAT CUSHION & BACK	(78)	GROUND
	ARMREST ON SEAT	(79)	WATER
(89)	UNDER SEAT BOTTOM		
(03)	· ·	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
(33)	RESTRAINT SYSTEM HARDWARE		OR WATER. PLEASE DESCRIBE.)
(34)	RESTRAINT SYSTEM WEBBING	Devem.	ATING OBJECTS
(34) (87)	AIR CUSHION SKIN (AIRBAG)		
, - ,		, ,	OTHER VEHICLE
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(72)	OBJECTS (DESCRIBE)
(46)	AIRBAG GAS		
(48)	KNEE RESTRAINT	MISCELL	
(30)	HEAD RESTRAINT		NO CONTACT (INVALID FIELD FORM CODE)
(42)	CHILD SEAT RESTRAINTS		OTHER (E.G. FIRE. DESCRIBE)
(43)	CHILD SEAT	(90)	SPARE TIRE
(31)	INTERIOR LOOSE OBJECT	(96)	INDUCED
•	OTHER OCCUPANT(S)	(97)	EJECTED, UNKNOWN CONTACT
(52)	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(96)	IMPACT FORCE, "WHIPLASH",
(41)	UNKNOWN INTERIOR SURFACE		HYPEREXTENSION/COMPRESSION
		(99)	UNKNOWN AREA OF CONTACT



INJURY CLASSIFICATION IC-4

CODES FOR OCCUPANT INJURY OF ASSISTEDATION (OIC)

	CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)								
1	BODY REGION	3	LESION	4	SYSTEMORGAN				
	(H) HEAD/SKULL		(L) LACERATION		(S) SKELETAL				
	(F) FACE		(C) CONTUSION		(V) VERTEBRAE				
	(N) NECK		(A) ABRASION		(J) JOINTS				
	(S) SHOULDER		(F) FRACTURE		(D) DIGESTIVE				
	(X) UPPER EXTREMITIES		(P) PERFORATION, PUNCTURE		(L) LIVER				
	(A) ARM (UPPER)		(K) CONCUSSION		(N) NERVOUS SYSTEM				
	(E) ELBOW		(V) AVULSION		(B) BRAIN				
	(R) FOREARM		(R) RUPTURE		(C) SPINAL CORD				
	(W) WRIST/HAND		(S) SPRAIN		(E) EARS				
	(C) CHEST		(D) DISLOCATION		(O) EYES				
	(M) ABDOMEN		(N) CRUSH		(A) ARTERIES				
	(B) BACK		(M) AMPUTATION		(H) HEART				
	(P) PELVIC/HIP		(B) BURN		(Q) SPLEEN				
	(Y) LOWER EXTREMITIES		(G) DETACHMENT,		(G) UROGENITAL				
	(T) THIGH		SEPARATION		(K) KIDNEYS				
	(K) KNEE		(Z) FRACTURE AND DISLOCATION		(R) RESPIRATORY				
	(L) LEG (LOWER)		(T) STRAIN		(P) PULMONARY/LUNGS				
	(Q) ANKLE/FOOT		(E) TOTAL SEVERANCE	CE.	(M) MUSCLES				
	(O) WHOLE BODY		TRANSECTION	,	(T) THYROID, OTHER ENDOCRINE GLAND				
	(U) UNKNOWN		(O) OTHER		(I) INTEGUMENTARY (SKIN)				
			(U) UNKNOWN		(W) ALL SYSTEMS IN REGION				
					(U) UNKNOWN				
2	ASPECT			5	SEVERITY				
	(R) RIGHT	ВО	SYS		(OR "AIS", ABBREVIATED INJURY SCALE)				
	(L) LEFT	DY 7	SE		(0) NONE				
	(B) BILATERAL	BODY REGION	SEVERITY SYSTEM/ORGAN LESION ASPECT		(1) MINOR				
	(C) CENTRAL	Ž	ST SE ST		(2) MODERATE				

- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

1 2 3 4 5

- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN









N3/32-98 #







t Available



r32-98 # t Available













2-98 #14



Available



t Availabl





Available

Bes









st Availab



t Available



5-80 67





12-30









CATE VO COLO STORM CATE VO COLO STORM Chierophile CCC.PAST (Below) 38 year eld female STATUS: 407 on: 58 4-649 MASS 79 kg (1984)0 STATUS Annier half serve stress destroyed



